

Doug Kelly

Eastgate Water Association

Well log as provided by Whidbey Drillers 11/26/02. The well was drilled in the early 1970s for Lowell Harrington.

Material	From	To
Hardpan	0	15
Sandy	15	80
Water sand (poor)	80	88
Sandy clay	88	108
Water sand (good)	108	136
Clay	136	

Static water level: 85' TOC

Screen: brass, set between 126 ft and 136 ft TOC.

Yield: 40+ gpm

33N/01E-24P